WITTENBORG

TECHNICAL INFORMATION

TYPE NO	TYPE	T.I.-NO
FB 2800	**Freshbrew machines with Classic brewer**	**FB. …01/2003**

SERIAL NUMBERS AFFECTED	ISSUED BY
From machine number 538520	**Documentation/ Wittenborg Odense**

SUBJECT	ISSUED FOR (X):	
Changed scraper switch	Action	
	Information	X

HEADLINES

- From the above machine number all FB 2800 machines in production have been provided with a changed scraper switch.

COMPONENTS CONCERNED

- **Changed part 29739000 Scraper switch**

MODIFICATION

- The design of the switch arm for the scraper switch - part no 29739000 has been modified.

REASON

- The switch arm of the scraper switch has been redesigned, as the design of the old switch arm caused start/stop errors on the brewer.

REPLACEABILITY

- The changed scraper switch is direct replaceable in all Classic brewers.



25.08.03	Grete jensen	25.08.03	Marianne Kristiansen
DATE :	PRODUCED BY :	DATE :	CHECKED BY :